TECHNICAL SHEET

POWER LED headlamp





REFERENCE
POWERLED



1. Press to turn on the headlamp and change modes
2. Press to activate motion sensor mode.
3. Press for 3 seconds to activate flashing mode.

Rechargeable by USB cable (Type-C charger)

Autonomy of 5 hours in high power

(Charging time: 2h)
3.7V/1200mAh Li-battery

IPX4 rating: LEDs can be used in heavy rain

350 Lumens
5 different lighting modes:
- Flashing
-High/Medium
-Side LED (high/medium)

Motion sensor mode (On/Off)

Dust resistant

adaptable to construction helmets

65 grams

www.surflex.eu